

Photographic Schedule: 101 Town Street, Nottingham NG1 3LY

Date taken: 02/10/2015

Please note: This is a small selection of our photos.

We have further photos retained on file and we reserve the right to reproduce these in the future if required.



Front Door



Entrance Hall



Light fitting with missing bulb



Reception Room



Reception Room



Chipped paint to ceiling



Chipped paint to Wall



Paint spot to carpet



Loose TV Point



Electric Fire



Paint splashes to Wallpaper



Dirt to edge of carpet

101 Town Street, Nottingham NG1 3LY



Kitchen



Kitchen



Scratches to Work Surface



Patch to vinyl Floor



Dirt to Kitchen window



Chipped paint to window cill

101 Town Street, Nottingham NG1 3LY



Under storage cupboard



Minor scuffs to Wall



Missing Vinyl to conrer



Stairs



Stairs



Landing

101 Town Street, Nottingham NG1 3LY



Carpet loose/come away from threshold



Bedroom 1 (Front)



Bedroom 1 (Front)



Window



Screw Holes above window



Paint spot to carpet


101 Town Street, Nottingham NG1 3LY



Minor chip to storage cupboard door



Mould to wall



Screw holes



Bedroom 2 (Rear)



Window



Missing bulb to light fitting

101 Town Street, Nottingham NG1 3LY



Paint patches



Furniture to carpet



Bathroom



Bathroom




Bath



Chipped paint to window sill in bathroom

101 Town Street, Nottingham NG1 3LY



101 Town Street, Nottingham NG1 3LY